



## Hyper Krome Ag & AgR Micro bottle USER INSTRUCTION

Thank you for purchasing Hyper Krome Ag Micro bottle.

Try and enjoy exceptional plating Krome never existed before!

Please read this instruction manual carefully before using the product.

**Store Hyper Krome Ag indoors at room temperature.**

**Make sure to keep it indoors during winter especially for those live in the extremely cold area.**

1. Lightly sand down with regular sand paper to precondition.

2. Paint Base Color Black

It is crucial to mirror polish the paint surface prior to apply base color.

Mirror polishing the paint surface plays a major role to achieve magnificent Krome plating finish.

Carefully paint the base color avoiding dusts and dirt.

Mix base color with 2k-thinner. If thinned with 1K type, make sure to apply 2K clear to harden.

Dry base color completely until harden. Summer: at least 24 hrs. at room temperature. Winter: at least 36 hrs. at room temperature

Do not touch while being dried. If touched, fingerprint will appear after topcoat is applied.

3. Paint HYPER KROME Ag

There's no need to mix HYPER KROME Ag, use it straight without mixing.

Again, do not touch the paint surface before spraying Hyper Krome Ag to avoid fingerprint to appear on the paint.

Spray lightly evenly. Once painted, brownish color appears however it will turn into Krome color as it dries out.

After the color turns to Krome, wait 2-3 minutes and spray another coat. Continue to spray 2-3 times and finish.

Maker sure to dry the paint completely until harden. Summer: at least 24 hrs.at room temperature. Winter: at least 36 hrs. at room temperature.

4. Paint Topcoat Clear

After drying HYPER KROME Ag until harden, paint topcoat clear.

Make sure to apply the topcoat at lowest pressure of spray gun and mist super dry and take 3-5 min interval, and repeat the same procedure 3-4 times and dry completely until harden.

Maker sure to dry completely. Summer: at least 24 hrs at room temperature. Winter: at least 36 hrs at room temperature.

After dried, spray semi-wet and wait further 5-10 min and spray wet to finish.

Although any clearcoat can be used, some may end up appearing bluish color.

Therefore we recommend to use our topcoat designed to perform well for Krome paint. (KRM-1KC)

## Hyper Krome Ag Frequently Asked Questions & Answers

Q	Seeing some bluish color after Ag was painted. (Before applying topcoat clear.)
A	Amount of Ag used per coat is exceeded.
Q	Seeing some yellowish color after Ag was painted. (Before applying topcoat clear. )
A	Lacking the amount of Ag used so increase the amount of Ag to use.
Q	Seeing some blackish color after Ag was painted. (Before applying topcoat clear.)
A	Base color was not cured completely.
Q	Is it OK to wipe down the dust after Base Color was applied?
A	After Base Color was applied, do not touch the surface as fingerprint will appear on top of Ag paint. It is recommended to re-paint base color if concerned.
Q	Is it OK to get rid of the oil / grease after Base Color was applied?
A	NO degreasing can be done as the pattern when degreased will show after Ag is painted.
Q	Like to know how to color Krome.
A	After Hyper Krome Ag was applied and finished with topcoat, sand down the surface and apply the Kandy color of your choice to make your desired color Krome.
Q	Bluish / yellowish color appeared after finished with topcoat as though Ag was painted nicely with good Krome color.
A	Either Ag and topcoat are not compatible or you applied the clear coat too wet from the 1 <sup>st</sup> spray.

### Precaution

- Keep out of reach of children.
- Shake the bottle until the liquid is completely agitated before use.
- After use, ensure to tighten the bottle lid completely and store in cool and dark place.
- Get medical attention immediately, in case of feeling sick, ill, unwell while using the product.
- Promptly wash eyes with plenty of water if inhaled or get in the eyes.
- Get medical help if irritation continues.
- Wear protective clothes such as masks, protective gloves and avoid inhaling the vapor for a long time.
- Keep the product in the cool place in order to avoid fire hazard.



Signal Inc., SHOW UP Division, 2-6-8 Aoshinke Mino Si Osaka, Japan 562-0024

<https://www.showup.jp/indexEg.html>

# HYPER KROME Ag 1K Kit User Instruction



Thank you for purchasing HYPER KROME Ag 1K Kit.

Please read the following precautions and instructions carefully before use.

It is a 1K (1-component type) paint that is ideal for hobby painting. Drying process is quicker from the base color to the top coat clear, and can be painted in a shorter amount of time than conventional two-component paint.

## Contents: HYPER KROME Ag 1K Kit

- ① HYPER KROME Ag Micro Bottle 15ml
- ② Special KROME 1K Base Color Black Micro Bottle 15ml
- ③ Special KROME 1K Topcoat Clear Micro Bottle 15ml

### 1. Paint Special 1K-type KROME Base Color Black

For Hyper Krome Ag, the more mirror the surface of the base color, the more beautiful the plating comes.

First, do the usual prep and paint the base color black avoiding dust and debris.

After painting the base color black, dry **at room temperature at 40~50°C about 2~3 hours, or 20~25°C with a household heater for about 24 hours or more.** Do not touch it during drying. If you touch it, fingerprints may come out from the place you touch after finishing with the top coat clear after Hyper Krome Ag paint.

### 2. Paint HYPER KROME Ag

Put the Hyper Krome Ag main agent (stock solution) in the spray gun as it is. (Dilution with thinner, etc. is not required at all.) )

Air blow without touching the dried Base Color black and paint HYPER KROME Ag.

Please paint with an airbrush or spray gun about 4~5 times from semi-dry or half wet.

Each interval should be at least 5 minutes.

Immediately after painting, a blackish-brown color appears, but while drying, it gradually changes to plating.

After applying Hyper Krome Ag, dry at a **household heater at 40~50°C for about 2~3 hours, or 20~25°C at room temperature for about 24 hours or more.**

### 3. Paint Special 1K-type KROME Topcoat clear

Paint Topcoat clear on top of dried Hyper Krome Ag.

First, spray super dry and mist state about 2~3 times.

Take the interval for about 5 minutes.

After painting super dry, dry again at **40~50°C about 2~3 hours, or 20~25°C at room temperature for about 24 hours or more.**

After drying, paint the Topcoat clear once semi-wet and finish to paint wet once.

Take intervals of about 5 minutes each.

#### Precaution:

- We recommend that you use this product within half a year after purchasing.
- Please use within 3 months after opening this product.
- Please understand that Hyper Krome Ag causes yellowing due to its oxidation characteristics of the paint.
- When storing Hyper Krome Ag, please store it indoors. Especially in winter, if you are in an extremely cold area, be sure to store it indoors without leaving it outdoors.
- The finish of Hyper Krome Ag depends on humidity. With brushing due to moisture and moisture in the air, the silver reaction of Hyper Krome Ag may be impaired. Please avoid painting on rainy days and other humid days as much as possible.

You can also watch the paint video from here ➡



Signal Inc., SHOW UP Division, 2-6-8 Aoshinke Mino Si Osaka, Japan 562-0024

<https://www.showup.jp/indexEg.html>